








OSAKA

MONTAGEVEJLEDNING / MONTERINGSANVISNING
MONTAGEANLEITUNG / ASSEMBLY INSTRUCTION







1






2



3








This diagram illustrates the assembly components for the 4602210-0500 part. It includes an exploded view of the main assembly, showing the main body, three long screws, and a small cylindrical component. A separate view shows the main body with a cross-section indicating internal structure. A curved arrow points from the main body to the exploded view, indicating the assembly direction. The part number 4602210-0500 is printed on the main body.

7



8

